



**HESTORE.HU**

elektronikai alkatrész áruház

**EN:** This Datasheet is presented by the manufacturer.

Please visit our website for pricing and availability at [www.hestore.hu](http://www.hestore.hu).

## TH-50111 Menu:

Code	Indicating	Set range	Initial Setting
P0	Mode set (Heat or Cool)	C/H	C
P1	Set return difference	0.1-15	2
P2	Up limit	-25...110	110
P3	Down limit	-30...105	-30
P4	Temp. Adjust	-7...7°C	0
P5	Delay start time	0-10 min	0
P6	High temp.alarm	ON/OFF	off
(P7)	High temp. alarm	0-110 C	off
(P8)	Initial setting	on/off	off

At "OFF" state, Long press + -,start and then recovery to initial set